



## Anton Art Center - Main Entry Sign

Location                    Mount Clemens, Michigan  
Designer / Architect     Nicolson Associates  
Duration                    Apr 2007 - Jun 2007

Scope - Soheil Mosun Limited was contracted to fabricate and install the main entry sign for the Anton Art Center in Mount Clemens, Michigan, USA.

Highlights - This project required the use of Aluminum, Bronze, Stainless Steel and Brass as well as varied finishes for each of these. The Artist's Palette Sculpture is waterjet cut 1/4" stainless steel with painted 1/4" aluminum elements, each mechanically mounted. The main structure is brushed stainless steel 1" square tubing with steel inserts in brushed brass footings. The ring and type graphics are waterjet cut 1/2" bronze with SML's special non-directional finish. The circular band and graphics are mechanically mounted to the chassis which is a brushed stainless steel square tubing structure forming a trois-foil design.



*Brass and steel footings*



*1/2" Waterjet cut bronze graphics mechanically mounted to a tig welded ring.*



*Ultra fine chassis welding is seamless*



*The finished sign, seen here on site, uses (4) different metals and has (4) different finishes.*



*Painted aluminum mounted to stainless steel*